

General Environmental Incident Summary

Incident: 1988 **Date/Time Notice:** 7/15/2013 1858 **DEM Incident No:**

Responsible Party: Enbridge Pipelines North Dakota

Date Incident: 7/15/2013 **Time Incident:** 1803 **Duration:**

County: Benson **Twp:** 156 **Rng:** 70 **Sec:** 15 **Qtr:** SE NE

Lat: 48.33278 **Long:** -99.64217 **Method:** Derived from TRS

Location Description: 2.5 miles NW of York

Submitted By: Ryan Stahler

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: paul calhoun
2505 16th ST SW
Minot, ND 58701

Distance Nearest Occupied Building: 1845 Feet

Type of Incident: Pipeline Leak

Description of Released Contaminant: Crude oil

Volume Spilled: 2.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Yes

Cause of Incident:

While doing an integrity dig, maintenance crews were hydrovacing and the inspector onsite noticed the smell of crude oil and shut down all work. The pipeline was immediately shut down and local operations were dispatched to the scene where at 6:03 pm CST it was confirmed that it was crude oil. Currently the release is estimated to be 2 barrels. Clean up crews are currently onsite working to remove contaminated soil and will be working throughout the night.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Contaminated soil to be removed.

Action Taken or Planned:

Pipeline shutdown, oil contained to ROW. Crews are onsite removing contaminated soil.

Wastes Disposal Location: Clean Harbors

Agencies Involved: NDDes, State Highway Patrol, Local Law Enforcement

Updates

Date: 7/16/2013 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

Site impacted surrounding soil and possibly ground water. Brady Espe will be responding 7/17/2013.

Date: 7/17/2013 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

The pipeline crews are working on digging up the soil that was impacted. More follow-up needed.

Date: 3/18/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

Received clearance sample results by hand delivery from company personnel. No further followup needed.